Nº 6716

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-11-57	IF SO HOW AND LOCATION FROM WYE 266 7027
HOUSE NO. 17.05	
SIZE OF PIPE USED C"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB7_/V0	
WAS ATTACHED TO MAIN Yels	NAME OF CONTRACTOR W. M. Mulan
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second s	g de la companya de
	('perly
	The first of the second of the
Ň	10 7 de
SIGNED Prof Justines For Ci	FILED AT ENGINEER'S OFFICE
	i ka kawa ka kuji ji ta shi a ni da ka sa iliya
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

6.56. No. 6716 ATT OF SE

PERMIT TO TAP SEWER

	MASSILLON	, OHIO. Geld	y 0 124200 40 191
RECEIVED OF Har	A Com	11 1	_ FEE OF 5 2 0C
FOR WHICH PERMISSION IS GRANTED	alex The	od	
TO TAP AMAIL	SEWER ON THE	South	
or Connections		1	•
THE PREMISES BEING LOT NO. 44	90-6491	, HOUSE NO.	705
WORK TO BE DONE IN ACCORDANCE		•	•
RULES OF THE DEPARTMENT OF PUBLI	16	•	
NAME OF CONTRACTOR ANTIL	1. 19. Weban		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.