

Nº 6719

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-10-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1165

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Repaired

0 - 201 012 /
1-24

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 6719

Relay

MASSILLON, OHIO, *July 17* 19*20*

RECEIVED OF *Jim Gulliss* FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED *Jim Gulliss*

TO TAP *saw* SEWER ON THE *south*

OF *Remont S.W.* AVE. ST. TYPE OF STREET *hard*

THE PREMISES BEING LOT NO. *7056*, HOUSE NO. *1105*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Ray Remley*

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.