Nº 6724

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED S-23-37	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. (04	· _		1 4
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	79'	81/2 De
WAS LATERAL AT CURBY			
WAS ATTACHED TO MAIN 1/0	- NAME OF CONTRACTOR	<u> </u>	Diana
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SER	VED.	
	ينه و المراجع المراجع المراجع المراجع المراج		20'
	en jaragan en jaragan en jaragan kanada k Tanada kanada kanad	anti versa na mar	17 dues
			<i>.</i>
egilen	and the public of the public of	sin service to part / 7"	w
<b>1</b>		9/2	
SIGNED Par Latham	FILED AT ENG	79'	
/ INSPECTOR FOR C	ITY FILED A ENG		
REMARKS			

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 6724

## PERMIT TO TAP SEWER

MASSILLON, OHIO, AND
RECEIVED OF FEE OF 5
FOR WHICH PERMISSION IS GRANTED (1) m Eddie
TO TAP LUN SEWER ON THE
OF De gart DE AVE. TYPE OF STREET dirt
THE PREMISES BEING LOT NO. 1/3/6 HOUSE NO. 604
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR LIAM A

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.