## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-28-57	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	""	7	7'020
HOUSE NO. 2/28			<i>F</i>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE S DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		•	-
WAS LATERAL AT CURB?	المراجع والمعارض والمعارض والمعارض والمسارة والمسار	er (Barris Bergaren 1997) Grand		
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR		1 Dia	nce
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SER	RVED.		•
	1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900	ing the state of t	20'	
		* 4 TO 160 4 TO 164 7 1	7 / 5-9'	'cup
SIGNED Por Latha	FILED AT ENG		E 11-15-	57
REMARKS	an illusori ( en trovistrativista.			

## Nº 6751

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, AL	4 15/5%
RECEIVED OF M. 4 D. Dulders, Juc. 1	1 FEE OF \$ 20-
FOR WHICH PERMISSION IS GRANTED	
TO TAP DAW SEWER ON THE MATTE	
OF alden M.W. AVE. TYPE OF STREET AIR A	
THE PREMISES BEING LOT NO. $11639$ House No. $2$	128
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY	Y THE CITY COUNCIL
NAME OF CONTRACTOR A LAMAN	
Note This permit covers work outside of building only.	Any work in

walls of building is subject to Massillon Board of Health Regulations.