FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-3-57	IF SO HOW AND LOCATION FROM (Y / 75 / 10 Deep P
HOUSE NO. 2207	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	in the control of the control of the state of the state of the control of the con
WAS ATTACHED TO MAIN /es	NAME OF CONTRACTOR A Dicina
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second of the second o	a de la companya de la constante de la constan
	17 olup
	The state of the property of the state of th
	101/28'seep
	The second of th
SIGNED Poy Lathons	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	Yan berkele and a serial seria
REMARKS	

Nº 6754

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, ALLA 15 19
RECEIVED OF M. 4 D. Sulders Jul. FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED
TO TAP DOWN SEWER ON THE MATTE
of Allin 7.11. AVE. TYPE OF STREET ALKA
THE PREMISES BEING LOT NO. 11642 , House No. 2202
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL.
Rules of the Department of Public Service.
NAME OF CONTRACTOR A DUANCE
Note This permit covers work outside of building only. Any work in

walls of building is subject to Massillon Board of Health Regulations.