## Nº 6761

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-/3-57 HOUSE NO. 6/8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 20 KASTO TOURS 71/2
WAS LATERAL AT CURB? VES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 9 Dinna
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	2n   neel
te production of the many tracking to the contract of the cont	16' 1/n Dee 10
SIGNED POY LOUIS INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
15 - 171 ( 21 ) 2 2	

## 2-171

## Nº 6761 PERMIT TO TAP SEWER

in the second se	e de de de graego de varia Como graego de Aleiro Massillon, Ohio,	7/1/
RECEIVED OF	M. J. Dinne	FEE OF \$
FOR WHICH PERMISSION IS	GRANTED HELD	
TO TAP Same	SEWER ON THE	er th
OF Leather	AVE.	
THE PREMISES BEING LOT		618
	0.0	
WORK TO BE DONE IN AC	CORDANCE WITH ORDINANCE No. 2323, DULY PAS	SED BY THE CITY COUNCIL.
RULES OF THE DEPARTMEN	NT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	a J. Kins	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.