Nº 6771 AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 10-1-57	IF SO HOW AND LOCATION FROM Harry Measure Mt. IS Not IN 819.
HOUSE NO. 59	-
SIZE OF PIPE USED 617	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBO Y 65	and a summary of the state of t
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR - Holling
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
	91
· John Marchael Barres	
	25' -5'2 deep
and the same and t	
SIGNED Poy & athe	FILED AT ENGINEER'S OFFICE
	A moving which is the first tenth than the closes
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, ALA 9 19
RECEIVED OF GLARA Nanther FEE OF 5 200
FOR WHICH PERMISSION IS GRANTED GLASIAC HISTORY
TO TAP PART SEWER ON THE TUPESA
of 234 9(1) AVE. ST. TYPE OF STREET Miled
THE PREMISES BEING LOT NO. 374/ HOUSE NO. 59
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR SURVEY B Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.