

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 6778

DATE INSPECTED 10-17-57

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** _____

HOUSE NO. 1707

SIZE OF PIPE USED 6"


**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** 63' 8' DEEP

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy L. Thoms
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

11-15-57

16-12

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6778

PERMIT TO TAP SEWER

MASSILLON, OHIO,

Oct. 15

19

RECEIVED OF

Harry B. Urban

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Donald Cap

TO TAP

main

SEWER ON THE

South

OF

Vermont St

AVE.

ST. TYPE OF STREET

West

THE PREMISES BEING LOT NO.

6258

, HOUSE NO.

1707

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry B. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.