FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10- 22-17	IF SO HOW AND LOCATION FROM TONDE TO 82' 5007	HOFM. 70.
HOUSE NO.		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	 Control of the second se	
· · · · · · · · · · · · · · · · · · ·	NAME OF CONTRACTOR A Winne	h.
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.	
en e	e di series de la companya del companya de la companya del companya de la company	
	The state of the second property of the secon	, <u>,</u> , ,
	The state of the second process and second s	17 pelen
	-0 12 4	1 Lydus
Pay Y	6" Ma1	'n 4"LAT.
SIGNED INSPECTOR FOR CITY	SANDER'S OFFICE	
REMARKS		

office of the director of public service PERMIT TO TAP SEWER

Massillon, Ohio,	21 19
RECEIVED OF A SUMMA	_ FEE OF \$ 2,
FOR WHICH PERMISSION IS GRANTED MILE ACTIVITIES	
TO TAP SAW SEWER ON THE SOUTH	
OF Aland 76 AVE. TYPE OF STREET siled	em este et personali
THE PREMISES BEING LOT NO. 5/55 , HOUSE NO. 5	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	THE CITY COUNCIL
NAME OF CONTRACTOR 1. Measia	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.