

Nº 6781

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-29-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1126

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 51' 7' DEEP

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR N. Urban

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Guthrie
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

8-17
18

8-17

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

No. 6781

MASSILLON, OHIO, Oct 23, 1918

RECEIVED OF Glick Bros. FEE OF \$ 2⁰⁰

FOR WHICH PERMISSION IS GRANTED Glick Bros.

TO TAP saw SEWER ON THE east

OF 14th P.W. AVE. ST. TYPE OF STREET dirt

THE PREMISES BEING LOT NO. 8925, HOUSE NO. 1126

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harry B. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.