

No. 6785

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-7-57

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Relay

HOUSE NO. 25

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

P. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS PELAY

7-39

7-39

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6785

PERMIT TO TAP SEWER

RELAY

MASSILLON, OHIO.

Nov 9

19

RECEIVED OF

Raymond Remley

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Wm Beresford

TO TAP

Sewer

SEWER ON THE

East

OF

23rd NW

AVE.

ST. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

7722

HOUSE NO.

24

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.