Nº 6807

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /- 20-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1022	<u> </u>	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE  PROMIN STREAM TO DITCH AT  CURB LINE AND DEPTH  CURB LINE AND DEPTH	1 2'04
WAS LATERAL AT CURB? YES	<u>and and a second control of the second cont</u>	
WAS ATTACHED TO MAIN // 0	— NAME OF CONTRACTOR	lani_
SHOW BY DIAGRAM RELATION OF LA	ATERAL TO WALL OF BUILDING SERVED.	
		//-
N		1-70mb
		18'
		- Tidell
Rail &		75'
SIGNED / INSPECTOR FOR	FILED AT ENGINEER'S OFFICE	
REMARKS	Primer is a literatura de la la companya de la literatura de la companya del companya de la companya de la companya del companya de la compan	

Nº 6807

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO. Jaw 16 19		
MASSILLON, OHIO, 19		
RECEIVED OF HOURY S UNAMED FEE OF \$ 2 -		
FOR WHICH PERMISSION IS GRANTED HOURS Sheken		
TO TAP Raw. / SEWER ON THE East		
OF 15-th DW AVE. TYPE OF STREET dist		
THE PREMISES BEING LOT NO. 1100 - Ph. 1979, HOUSE NO. 1022		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL		
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR HATTHU & Wikaw		

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.