FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 3-19-68 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
ноиse no// о З	
SIZE OF PIPE USED 6" CURB LINE AND DEPTH 23 110 51 REAM M	4. 6 De
WAS LATERAL AT CURB? Yes	
WAS ATTACHED TO MAIN NAME OF CONTRACTOR P Man	Ro
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
and the second of the control of the	H
or an armine the second of	
Telpole Live	WO .s
N o	BENDO
O_{-} , \mathcal{G}_{-}	035
SIGNED FILED AT ENGINEER'S OFFICE	<u> </u>
A CONTROL OF THE PROPERTY OF T	

Nº 6815 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, March	18 19
RECEIVED OF 9.	marks	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Frustaci	
TO TAP SE	EWER ON THE ANTA	
of andork S.W. AVE. T		unface
THE PREMISES BEING LOT NO. 11 7. 99		/3
WORK TO BE DONE IN ACCORDANCE WITH ORDIN	ANCE NO 2222 DULY BARRED BY T	HE CITY COUNCIL

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.