

Nº 6829

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-16-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 630

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

89' 8' deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. R. Penley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
↑



80'

5'

89' →

SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

76 35
32

4-10-3

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

No 6829

MASSILLON, OHIO,

April 16

19

RECEIVED OF

Ray Remley

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

R. J. DePan

TO TAP

san

SEWER ON THE

North

OF

Sherrill NE

AVE.

ST. TYPE OF STREET

Acres

THE PREMISES BEING LOT NO.

11469

HOUSE NO.

130

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ray Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.