

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 6831

DATE INSPECTED 4-19-58

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** _____

HOUSE NO. 1721

SIZE OF PIPE USED 6"


**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** 139' 10' 0" or 10'

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR R R Rumber

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

16-23

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 6831

PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/18 1918

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED L. C. Moser

TO TAP Law

SEWER ON THE 1st

OF Cornell 71 E

AVE.

ST. TYPE OF STREET Hard surface

THE PREMISES BEING LOT NO. 10164

HOUSE NO. 1721

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.