Nº 6843

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-21-58	_ IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. // 0 /		
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DISTANCE FROM FIRST MANHOLE OURS LINE AND DEPTH 15 UP STREAM M.	6/20,
WAS LATERAL AT CURB? V-CS	in de la completa de En la completa de la	
WAS ATTACHED TO MAIN /VO	- NAME OF CONTRACTOR - NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
e de la companya de la manda de la manda de la Maria de la del Maria de la Maria de la Maria de la Maria de la La manda de la	18	
	Town	
i produktifijes. Auforzalie austroperatur vol. Parkolokaa ir kora (1906) on too oo		511
	The second section of the section of the section of	96
	<u></u>	12 6
	up String >	15'
SIGNED Poy Vatham	FILED AT ENGINEER'S OFFICE	
·	iry Li wajisakan il kajisakijika bi tekli ilokalisi aliaw	
REMARKS		

8-23

NO 6843 PERMIT TO TAP SEWER

MASSILLON, OHIO, MAIN 21 19
RECEIVED OF HARAIL 19 HISTORY FEE OF & 25
FOR WHICH PERMISSION IS GRANTED QUALITY THE SHOW
TO TAP DAIL SEWER ON THE West
OF 15 the 1,111. AVE. TYPE OF STREET AUX
THE PREMISES BEING LOT NO PART O As 276, HOUSE NO. 1101
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.