

1716
111

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 6854 AND SIGNED WHEN RETURNED**

DATE INSPECTED 6-12-58 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Relay 4' OF P.I.P.

HOUSE NO. 821


SIZE OF PIPE USED 4" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN no

NAME OF CONTRACTOR R. Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

8-11-58

14-2

Relay
Nº 6854OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/17 19

RECEIVED OF R. Barney

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED G. H. W. W. W.

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

9939

HOUSE NO.

821

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Relay

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.