FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-55	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBI	and the second of the second by the second of the second o
WAS ATTACHED TO MAIN 10	NAME OF CONTRACTOR————————————————————————————————————
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
N	
	the second contraction is the second contract of the second contract
	80°
n C	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	and the first of the manufactual of partial of the first

-11-5

10 = 3

Nº 6868

PERMIT TO TAP SEWER

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	\mathcal{A}	
	Massillon, Ohio, $\frac{7}{7}$	į.
	RECEIVED OF FEE OF \$ 2	ť
	FOR WHICH PERMISSION IS GRANTED A 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	
1	O TAPSEWER ON THE	
	OF AVE. TYPE OF STREET	-
. 1	THE PREMISES BEING LOT NO. 1111	
١	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL	,

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR_____

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.