## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR and signed when returned

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN SIREAM	
HOUSE NO.		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
: : : : : : : : : : : : : : : : : : :	는 사람들은 "하여 유전하면 사람들은 마리가 함께 하는 사람들은 전문에 있는 것이다면 하는 사람들이 있는 사람들이 있다고 있을 것이다. 이 계약을 모든 사람들이 없는 것을 하는 것을 것을 하는 것을 하는 것을 하는 것을 하는 것을 것 하는 것을	,你没有你说话,我
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.	
SHOW BY DIAGRAM RELATION OF	F LATERAL TO WALL OF BUILDING SERVED.	
SHOW BY DIAGRAM RELATION O		
SHOW BY DIAGRAM RELATION OF	F LATERAL TO WALL OF BUILDING SERVED.	
SHOW BY DIAGRAM RELATION O		
	en e	V
		¥
	en de la desperación de la composición del composición de la compo	¥

REMARKS

## Nº 6870

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLO	n, Оню,	4	19.
RECEIVED OF Manager	quescal.	FEE O	)F <b>\$</b>
FOR WHICH PERMISSION IS GRANTED E	eri e e kaliforni je u mananjagajimi tao liberi a fano i		
TO TAP 1 1701 SEWER ON THE	156000	<u> </u>	
OP TO STREET	er. ///		
TAILERY KANE 100.		116	(Call)
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 23	323, DULY PASS	SED BY THE CI	TY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR			and the second s

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.