Nº 6872

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-23-37	IF SO HOW AND LOCATION FROM
and the second of the second o	FIRST MANHOLE DOWN STREAM
HOUSE NO. 1930	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURBY 95	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Traple Eyea.
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	RAL TO WALL OF BUILDING SERVED.
N <del></del>	70 × 10 × 10 × 10 × 10 × 10 × 10 × 10 ×
•	90
	P / 160
SIGNED ROY X the	FILED AT ENGINEER'S OFFICE
(NSPECTOR FOR CIT)	milet ha in de speljing ei geljalent ha a vær
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

7.3 HOUSE NO. / 9.30

## Nº 6872 PERMIT TO TAP SEWER

THE PREMISES BEING LOT NO. / //a WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.