## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR No. 6886 AND SIGNED WHEN RETURNED

DATE INSPECTED 8-19-58 IF SO HOW AND LOCATION FROM 11 /// 5 0.
HOUSE NO. 550
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 10
WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR JOH Y Joh
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
And the second s
14'
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
0 111'
SIGNED Roy Yatham FILED AT ENGINEER'S OFFICE 50 9-18-58
TIME CONTROL OF THE PROPERTY O

## Nº 6886

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, OLO 15 19
RECEIVED OF ACT THE FEE OF \$ 200
FOR WHICH PERMISSION IS GRANTED III & DUISAGES A.
TO TAP DEW SEWER ON THE A SUITE
OF
THE PREMISES BEING LOT NO. 3 MAIRRALLES, # 4, HOUSE NO. 550
// HOUSE NO.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE,
NAME OF CONTRACTOR ME Y HAR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.