FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-22-5	FIRST MANHOLE DOWN STREAM	64'	7/0
HOUSE NO. 2/36			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURBI	 M. Martin, E. Company, Phys. Lett. B 1997, 1997, 1997, 1997, 1997, 1997. 	4.5	
WAS ATTACHED TO MAIN VOS	NAME OF CONTRACTOR	V Ores	1
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	σ	
			2
	70-1		
	191 75	641	
SIGNED Roy Kath	FILED AT ENGINEER'S OFFICE	9-27-	58
/ INSPECTOR FOR CIT			
	The state of the s		

Nº 6904

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 15 19
RECEIVED OF THE 4 PRO FEE OF \$ 5 -00
FOR WHICH PERMISSION IS GRANTED HILLY D. BUILDERS
TO TAPSEWER ON THE
OF PRINCIPAL MU AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. # 21 Mart Mayer 4 YHOUSE NO. 2136
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR ALL Y

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.