

Nº 6911

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-20-58

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

21' 9' deep

HOUSE NO. 1803

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

G. Piccini

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N

MAIN SEWER UNDER  
SIDE WALK

21'

40'

14'

8'

7'0"

9'0"

SIGNED

Roy V. Athans  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

7-5

7-16-21

CITY OF MASSILLON, OHIO

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N<sup>o</sup> 6911

PERMIT TO TAP SEWER

5 apt.

MASSILLON, OHIO,

August 25, 1921

RECEIVED OF

N. &amp; D. Builders

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

N &amp; D Builders

TO TAP

Sewer

SEWER ON THE

South

OF

Ludlow W.

AVE.

ST. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

4880

HOUSE NO.

1813

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL,  
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Slavin

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.