Nº 6912

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-23-58 HOUSE NO. 184	DISTANCE FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6	CURB LINE AND DEPTH SDEEP
WAS LATERAL AT CURB? YES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H. URBAN
SHOW BY DIAGRAM RELATION OF LATE	
	80 100
SIGNED William E. 3660	FILED AT ENGINEER'S OFFICE 10-79-58
REMARKS	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

TA A	6912		PEKM	11 10	TAP SE	WEK	
			.√ MAS	sillon, Ohio,	9/5	er elæt temmet j	.19
REC	EIVED OF	elm 1	look)			FEE OF 5	<i>I</i> C
FOR WHICH	1 PERMISSION I	5 GRANTED	Gen 1	m = 0	One O	je de jako	
TO TAP	M. Lace	м <u>.)</u>	SEWER O	N THE	77	Ali di baran english kaling. Ali di saman di saman saman di saman saman di saman sama	
OF	1 6 h	1518	AVE. ST. TYPE OF	STREET	dort		
THE PREMI		No. // 3		and the factor of			1
	U V	CCORDANCE WIT				7	CIL
Rules of	THE DEPARTM	ENT OF PUBLIC S	ERVICE.				

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.