

Nº 6926

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 265

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 289' 6 1/2' De

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR N. Hibon

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

135-78
16-28

11-10-58

Nº 6926

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Sept 29 19.

RECEIVED OF

Carl Riser

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Carl Riser

TO TAP

San

SEWER ON THE

South

OF

Gail NE

AVE.

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

PT. 01. 384

HOUSE NO.

265

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry B. Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.