## $N_{\odot}$ 6930

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-9-58	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2/4/		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES	- Company of the Comp	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR Harry Urban	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.	
and the second s	103 4 60	
e de la composition de la composition La composition de la		N
es mant pas effect of paint to ex-	and the commence of the commen	
		-
	/ 76	•
1.0 4 0	K /38	
SIGNED Williams & White	FILED AT ENGINEER'S OFFICE	10-79-58
INSPECTOR FOR	Till not be extil to i secioles on extilination of her	
REMARKS THRRED IN PLUS 3'F	ROM HOUSE	•

16-37

Nº 6930

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	ing ang Palatan ang Palatan ang Palatan Palatan ang Palatan ang Palatan ang Palatan Palatan ang Palatan ang Pa	Alteria Neglecies A Massillor	I, OHIO, OU	18
RECEIVED OF	. Harry	B Wisto	711)	FEE OF \$ 2 -
FOR WHICH PERMISS	ION IS GRANTED	.C. 500C	Fadden	
TO TAP 10 11		SEWER ON THE	Mest	
OF ILLAND	and the state of t	AVE. _ ST, TYPE OF STREE	τ // (1/d	
THE PREMISES BEING	1 LOT NO. 1/34		., HOUSE NO	141
WORK TO BE DONE	IN ACCORDANCE WITH	ORDINANCE No. 23	23, DULY PASSED BY	THE CITY COUNCIL,
Rules of the Depa	RTMENT OF PUBLIC SE	B. Waba	и	

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.