Nº 6939

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그	O HOW AND LOCATION FROM ST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	TANCE FROM FIRST MANHOLE VN STREAM TO DITCH AT RB LINE AND DEPTH	143'	7'Dec
WAS LATERAL AT CURB? Yes	lli oʻgʻilgili ildə təqqəni əsa kasarı.		
WAS ATTACHED TO MAIN NO NA	ME OF CONTRACTOR	REMLE	<u>Y </u>
SHOW BY DIAGRAM RELATION OF LATERAL	TO WALL OF BUILDING SERVE	ED.	
		17' 7' DEEP	
SIGNED ROY Vathans	P 713	EER'S OFFICE 12-8-5	- 58
/ INSPECTOR FOR CITY REMARKS	FILED AT ENGIN	EER'S OFFICE 120	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6939

PERMIT TO TAP SEWER

		ar e feli al a g		MASSILLON	, оню,		19,
		F	19	. ,			3 00
	RECEIVED OF		and to a Land	Wart.	<u> </u>	FEE	of \$
			\mathcal{A}	40	8/11		
FOR W	HICH PERMISS	ION IS GRANT	ED	· 2 10 141 15 1		Marie Carlos Car	
TO TAE	. <i>D</i> .		9	EWER ON THE	E		
OF		<i>tl</i>)) W AVE. T	YPE OF STREE	:	122	
THE PI	REMISES BEING	LOT NO	7088		., HOUSE NO	4.30	
WORK	TO BE DONE	IN ACCORDA	NCE WITH ORDIN	IANCE NO. 23	23, DULY PAS	SED BY THE C	ITY COUNCIL,

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Den

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.