Nº 6950

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-10-5-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED (2)	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH GOES 7 0 7 0 7 0 7 0 7 0 0 1 1 1 1 1 1 1 1 1 1 1
WAS LATERAL AT CURBY YES WAS ATTACHED TO MAIN NO.	NAME OF CONTRACTOR HOLD BAN
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	26 (ch) = 000
SIGNED Non Mil An	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	

638-36

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	0 1 1 10 10	SSILLON, OHIO,	1140 5
RECEIVED OF	S Garage	, Hastler	FEE OF 5
TO TAP DAUL	SEWER (ON THE	11 C
or Man M	AVE. ST. TYPE OI	- STREET	141
THE PREMISES BEING LOT NO.	11474	, HOUSE NO.	510

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.