## Nº 6954

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-7-5-8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 126			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	161' 6/2'	0000
WAS LATERAL AT CURB? Ves	and the grade and the state of the second section of the section of the second section of the section of the second section of the sectio	e santa da Aria. Tanàna ao amin'ny faritr'i Amerika	1
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	A DIAN	<i>H</i>
SHOW BY DIAGRAM RELATION OF LATE		<b>)</b>	
		5/20	
		109' N C/2 D	
	· · · · · · · · · · · · · · · · · · ·		
SIGNED Www Wh	FILED AT ENGINE	ER'S OFFICE	7
INSPECTOR FOR CI	TY	THE REPORT OF THE	

6-30

6954

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

interfection of the Conference	MASSILLON, OHIO, //Members 6 19
RECEIVED OF	Wenne FEE OF \$
FOR WHICH PERMISSION IS GRANTED	un Samhin
	EWER ON THE
OF 6 St. M. M. AME. T.	YPE OF STREET And Auch
THE PREMISES BEING LOT NO. 1116	, HOUSE NO.
	NANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	[발표학 등 교실에 변환하는 10일 현황 [

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.