Nº 6957

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $\frac{4-1-39}{}$	IF SO HOW AND LOCATION FROM LAT. 3' NORTH OF FIRST M	4 5007 HOF
HOUSE NO. 498	<i>vp</i>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTM	
WAS LATERAL AT CORBY YES	and the state of t	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR P. Pemler	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	T
	RAL TO WALL OF BUILDING SERVED. C/F2/1007 BFN0 5/- 2' PIDE GX 4" WYC WA-4 FIDE CX 4" WYC W	**************************************
	The color and a light was been a private to the	<u>.</u>
Market Ma	$c^2/\sqrt{16}$	
<i>N</i>	Prophing / Bazi	
P. U.	7 3' 4	
SIGNED / M albamy	FILED AT ENGINEER'S OFFICE	
	The Hapethalog and the property of the Happy before the control of	
REMARKS		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR

6957

Note This permit covers work butside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.