

Nº 6972

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-20-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 201

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE MEASUREMENT 49'
DOWN STREAM TO DITCH AT FOUND LAT 51' 30" DE
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR H. URBAN

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

3-32-33

11-22-58

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 6972

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/19 19

RECEIVED OF

Harry Larkin

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Municipal Sewer

TO TAP

Ave

SEWER ON THE

OF

Lake NE

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

Plat 96-1-E

HOUSE NO.

201


WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. Larkin

Note: This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

6" Pipe Insp 11-19-58



GRUNDEN LAID PIPE FOR BEAVER EXCA

2630272
2e 3-3304

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6971

PERMIT TO TAP SEWER

MASSILLON, OHIO.

11/19

1958

RECEIVED OF

Deaner Excavating Co

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Earl Calhoun

TO TAP

San

SEWER ON THE

W

SIDE

OF

Suggart N E

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

113.51

HOUSE NO.

605

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Deaner Excav. Co

Note This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

17-17

No 6970

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. outside City

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

90' 9' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR

R R FENLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-8-58

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6970

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/17/19

RECEIVED OF

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

#3

WOODCREST

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

Nº 6969

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2424

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

IN MH 17' WEST 4'D


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy L. Thann
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-8-58

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 6969

PERMIT TO TAP SEWER

MASSILLON, OHIO,

19

RECEIVED OF

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

Nº 6968

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-9-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

IN DEAD END MH 7'0

HOUSE NO. 330

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

IN MH


WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

R REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N 



SIGNED

Roy Vatham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

11-22-36

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

No. 6968

Convent for Sisters

MASSILLON, OHIO,

11/17

19

RECEIVED OF

R. Ramsey

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

St. Joseph's Church

TO TAP

San

SEWER ON THE

E

OF

4th St. NE

AVE.

ST. TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

2915-16

HOUSE NO.

330

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Ramsey

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

No. 6967

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-29-58 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 617

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 307' 3' DEEP
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN Yes NAME OF CONTRACTOR P. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham FILED AT ENGINEER'S OFFICE

INSPECTOR FOR CITY

REMARKS _____

13-39

11-22-58

No 6967

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWERMASSILLON, OHIO, 11/17 19RECEIVED OF R. RamseyFEE OF \$ 2 ¹⁴ -FOR WHICH PERMISSION IS GRANTED Al MichaelTO TAP LineSEWER ON THE EOF Waller Pl

AVE.

ST. TYPE OF STREET drivTHE PREMISES BEING LOT NO. 11287HOUSE NO. 612WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Ramsey

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

No. 6966

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-14-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 374

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

68' 6' deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

R REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

11-22-58

16-3-2

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 6966

MASSILLON, OHIO,

19

RECEIVED OF

R. Ramsey

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

John Hollenback

TO TAP

San

SEWER ON THE

E.

OF

Highway 1 E

AVE.
ST.

TYPE OF STREET

dist

THE PREMISES BEING LOT NO.

11618

HOUSE NO.

374

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ramsey

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.

No. 6965

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-12-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1714

SIZE OF PIPE USED 6"




DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 45' 7' 0"

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. REMLEY

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

11-15-58

16-1443
N^o 6965

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, November 10, 1958RECEIVED OF Richard Remley FEE OF \$ 21E. FOR WHICH PERMISSION IS GRANTED Richard McQuinnTO TAP San SEWER ON THE NorthOF Massachusetts AE AVE. ST. TYPE OF STREET StreetTHE PREMISES BEING LOT NO. 6316, HOUSE NO. 1714WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR RemleyNote This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**



IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

SIZE OF PIPE USED 6" UP DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS ATTACHED TO MAIN 110

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

11-15-58

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

16-74-13
Nº 6964

PERMIT TO TAP SEWER

MASSILLON, OHIO, November 10 19RECEIVED OF Raymond Bender FEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED E. L. McQuinnTO TAP San SEWER ON THE NorthOF Massachusetts Ave. AVE. ST. TYPE OF STREET WestTHE PREMISES BEING LOT NO. 6318, HOUSE NO. 1706WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.NAME OF CONTRACTOR Raymond Bender

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

Nº 6963

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-10-58

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1624

SIZE OF PIPE USED 6" x 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN N/O

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

R. RAMLEY



SIGNED

Wm. White

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

16-14-13

11-13-3'

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 6963

MASSILLON, OHIO, Nov 10 1919

RECEIVED OF Raymond L. ... FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED Harold E. Mc ...

TO TAP San SEWER ON THE north

OF Massillon AVE. ST. TYPE OF STREET dist

THE PREMISES BEING LOT NO. 6321 HOUSE NO. 1624

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR ...

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.