Nº 6998

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-11-59	IF SO HOW AND LOCATION FROM 1 Y"/3' WEST 7 DEED
HOUSE NO. 2/50	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE.  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Que Y Var
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
p. of To	
SIGNED / SIGNED / INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
REMARKS	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

		Ż	1: 1	47		:	/i	7.3	ď		i.	
:		Ń	Ţ	0	. 1	•	(	)	9	9	8	
									7		_	
		1,			٠.		1	٠.	١.			
	٠.	٠	•	٠,			ť,				13.	٠.

## PERMIT TO TAP SEWER

		Massillon, Ohio,	//0
	RECEIVED OF		FEE OF S
Noul	FOR WHICH PERMISSION IS GRANTED	I D Blow	
	TO TAP Lan SE	EWER ON THE	
	of Manager of St. T	YPE OF STREET	
	THE PREMISES BEING LOT NO. $1/907$	HOUSE NO.	1.50
	WORK TO BE DONE IN ACCORDANCE WITH ORDIN	ANCE NO. 2323, DULY PASSED I	BY THE CITY COUNCIL
He.	NAME OF CONTRACTOR	4 0	
	Note This permit covers work	outside of building only	Any work in

walls of building is subject to Massillon Board of Health Regulations.