

No. **7017**

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-29-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1019

SIZE OF PIPE USED 6" UP

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

60' NORTH OF MH @ KORN 7' D


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR


R Ramsey

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



UPSTREAM
MH
↓

155T



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 7017

8-23
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 22 1919
RECEIVED OF Ray Reuley FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Sewer Taps
TO TAP Sewer SEWER ON THE West
OF 15th P.W. AVE. TYPE OF STREET Dist
THE PREMISES BEING LOT NO. R 276-E, HOUSE NO. 1019
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Ray Reuley

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.