

No. 7023

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-14-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 726

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 5'6" North of 1st MA North
of over 60

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN no

NAME OF CONTRACTOR R Rensley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

3-12-11
7-21
N^o 7023

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 24 1919

RECEIVED OF Raymond Reimling FEE OF \$ 2.

FOR WHICH PERMISSION IS GRANTED F. W. Harvey

TO TAP San. SEWER ON THE east

OF Harmon St. S.W. AVE. ST. TYPE OF STREET hard surface

THE PREMISES BEING LOT NO. 4695 - Pt 4694, HOUSE NO. 726

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Reimling

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.