

N^o 7052

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-10-59IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 2123SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 205' H.P. CARVEY 8' D.E.WAS LATERAL AT CURB? YesWAS ATTACHED TO MAIN N/ANAME OF CONTRACTOR Joe Y Joe


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

Roy K. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____



3
Nº 7052

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 18 19

RECEIVED OF

M & A Bldg

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

M & A Bldg

TO TAP

San.

SEWER ON THE

South

OF

Whitman N.W.

AVE.

ST. TYPE OF STREET

Dist

THE PREMISES BEING LOT NO.

11916

HOUSE NO.

2123

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Jac & Joe

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.