## Nº 7060

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

•	· · · · · · · · · · · · · · · · · · ·
DATE INSPECTED 5-26-5-9	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2/52	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH 201 END LAT. 36 LONG 8 DEE
WAS LATERAL AT CURB?	188' & wy e
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.
Y Y	
	>0 \ 5
arako araba karako 🏪	
4	80 %
	34 188'
SIGNED_Roy Lather	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR C	Taptak saa up ne jouz 11 pail lak be attest   1-7-60
REMARKS	
	antara de la companya del companya della companya

Nº 7060

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILI	ON, OHIO, Mars 18 19
RECEIVED OF 114 A Bld.	1 FEE OF \$ 2:
FOR WHICH PERMISSION IS GRANTED 76	Blden,
TO TAP SEWER ON THE	HE narth
OF Adjustant 71.11. AVE. TYPE OF STE	EET ALST
THE PREMISES BEING LOT NO. 11935	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No.	2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	·
Note This permit covered work outside	of building only. Any work is

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.