Nº 7118

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-36-59	IF SO HOW AND LOCATION FROM TAN 2/3 WEST STIST MANHOLE DOWN STREAM TAN 2/3 WEST STIST MY WEST CA
HOUSE NO. 2/4/	The state of the s
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB7	and the second of the second o
	NAME OF CONTRACTOR. See, More
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	· /7 '
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
egi ere ere ere ere ere ere ere ere ere er	
State of the state	
· N	TAP WITH SA
, ·	TEPL,
	213 X8/2/2000 875° 18/5 NO
SIGNED Northeyn	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY	and the safe and the safe in t
REMARKS	

Nº 7118

PERMIT TO TAP SEWER

	Massillon,	Онто,	0/10	 19
RECEIVED OF	Bldra		FEE (of \$
FOR WHICH PERMISSION IS GRANTED	Magaz	•		
TO TAP	'	Ĵ		
of Maiklower Mi	AVE.	1	1	
THE PREMISES BEING LOT NO.				
WORK TO BE DONE IN ACCORDANCE WITH RULES OF THE DEPARTMENT OF PUBLIC SE		3, DULY PASS	ED BY THE C	ITY COUNCIL

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.