Nº 7135

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

•	in the second se
DATE INSPECTED 5-27-59	IF SO HOW AND LOCATION FROM TAP 358 WEST OF IST MANNET OF C
HOUSE NO. 2/50	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 10	and the second of the second o
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR SOO, V Joe
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	<i>'</i> , ', ', ', ', ', ', ', ', ', ', ', ', ',
	1 n'deep
and the principle of the control of	
	TAPWITH SAPILE 186 8960 B-ND 11/2000
SIGNED Ray Vathom	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY	grafikket forest i net farest i allef sed kenst næt

No 7135 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	Massillon, (OHIO, 19
	RECEIVED OF M+ D. Bldro	FEE OF S
	FOR WHICH PERMISSION IS GRANTED A 11 me	
U	TO TAP (t) SEWER ON THE	<u>n </u>
	OF Mark Land Mil AVE. TYPE OF STREET	dist
÷.	10 01	HOUSE NO. 2 /57
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323	3, DULY PASSED BY THE CITY COUNCIL

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.

NAME OF CONTRACTOR