

Nº 7141

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

STUB IN MANHOLE 7' DEEP

HOUSE NO. 2112

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Joe V. Gue

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

8-41

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 7141

PERMIT TO TAP SEWER

MASSILLON, OHIO,

8/10

19

RECEIVED OF

N. A. Belles

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Sumner

TO TAP

San

SEWER ON THE

N.

OF

Maplewood NW

AVE.

ST. TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

12015

HOUSE NO.

2112

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Joe + Joe

Note This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.