Nº 7145

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-11-5-9	FIRST MANHOLE DOWN STREAM HOOKED IN 14	/ <u> </u>
HOUSE NO. 2425	_	**************************************
SIZE OF PIPE USED 211	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	3
WAS LATERAL AT CURBI NO	and the community of the company of	
WAS ATTACHED TO MAIN VOS	- NAME OF CONTRACTOR Results	, , , , , <u>, , , , , , , , , , , , , , </u>
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	
· · · · · · · · · · · · · · · · · · ·		
	23/4	
	1 / Deep	>
exilia a di indica a les este de est i i estis in	is a beautiful order of the west force and increasing of the	
·	10/2	
The second secon	A 11'-3	
SIGNED Winn White	FILED AT ENGINEER'S OFFICE	44
INSPECTOR FOR C	HTY	11.
REMARKS Realt of Hous	and the contract of the second se Property second s	

1-2-39

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO,
RECEIVED OF LAND KINGLEY FEE OF \$ 2-
FOR WHICH PERMISSION IS GRANTED PARALLE MARKETS
TO TAP_ SEWER ON THE SOUTH
OF Woudlice, 91. W AVE. TYPE OF STREET AUST
THE PREMISES BEING LOT NO. 3827-3828 , HOUSE NO. 2425
THE FREMISES SEINS LOT NO. COS ST. T. S.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR AND ALLULLY

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.