Nº 7146

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

4		*** ***
DATE INSPECTED 8-18-89	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	<u> </u>
HOUSE NO. 336		
SIZE OF PIPE USED 611 UP	DISTANCE FROM FIRST MANHOLE -BOWN STREAM TO DITCH AT GURB LINE AND DEPTH 25 WEST > 70	PSTREAM! 7'
WAS LATERAL AT CURBI Y 6 5	$(x,y) = (x,y) \in \mathbb{R}^{n}$, where $(x,y) \in \mathbb{R}^{n}$, where $(x,y) \in \mathbb{R}^{n}$	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	eaver
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
	A S	7'
and the same of the contract o	The second seems described by the property of	. 1
	Section of the sectio	and the second second
		251
SIGNED Part Wather	FILED AT ENGINEER'S OFFICE.	
MSPECTOR FOR CIT	residencia es suciebra a gesti de la la religio	•
REMARKS		

Nº 7146

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Reci	EIVED OF		Our of	L. O.	FEE OF S
		Ě		/0 <i>f</i>	
TO TAP	PERMISSION IS GRAN		SEWER ON TH		00
or	2962)) (AVE	TYPE OF STRE	et O	Zaran in Angel
THE PREMIS	ES BEING LOT NO.	1375		, HOUSE NO.	3.0
WORK TO B	E DONE IN ACCORD	ANCE WITH OR	DINANCE NO. 2	323, DULY PASSE	BY THE CITY C

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.