

Nº 7156

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-28-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1313

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST-MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

93' W. OF M @ 13' H. 8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

W. Bogel

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Yatham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

9-30-30 8-19
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Permit No. 7156

PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 25 1930

RECEIVED OF

Livaudale, Alders

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

San.

SEWER ON THE

South

OF

Livaudale Ave.

AVE.

ST. TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

9020- Pt 9019

HOUSE NO.

1313

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

D. Rager

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.