Kelay

at curt of

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-8-9	IF SO HOW AND LOCATION FROM // WAS TO	6'I T'DEAN END M
HOUSE NO. 621	THE HARMELE BOWN STREAM	N - 41 17 134 17 19
SIZE OF PIPE USED 4111/611	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURBA NO	in the second of	
WAS ATTACHED TO MAIN / AS	NAME OF CONTRACTOR	lann
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.	
	The state of the s	LXAY COOP
	SOUTHOURS TOOTO	CXA
The second secon		YO'SL' 95 OBEND C'D.
A Company of the Comp	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	<del> </del>
SIGNED Pry Lathons	FILED AT ENGINEER'S OFFICE	
REMARKS 411 LAT. HODE	ed 010 to Mow Seiner ON SOUT!	4810-1251

11.70

## office of the director of public service PERMIT TO TAP SEWER

	MASSILLON, OHIO, Catalin 2 19
RECEIVED OF Flavoure	Krah. FEE OF \$ 20
FOR WHICH PERMISSION IS GRANTED 46	
TO TAPSEW	
OF Carles S.W. AVE. TYP	and the second of the second o
THE PREMISES BEING LOT NO. 33414	, HOUSE NO. 62/

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

IAME OF CONTRACTOR C. J. Manager

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.