

Nº 7162

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-15-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 50

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 197' 6 1/2' DEEP

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR H. Wilson & Roberts

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7162

PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 13, 1919

RECEIVED OF Larry J Urban FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED (Carl Ross)

TO TAP raw SEWER ON THE east

OF 112th St AVE. TYPE OF STREET hard surface

THE PREMISES BEING LOT NO. Pt 4960-4959, HOUSE NO. 50

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Larry J Urban

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.