

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 7169 AND SIGNED WHEN RETURNED

DATE INSPECTED

10-20-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

WYE 124' E. OF M @ 140' 9"

HOUSE NO.

1318

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

No


WAS ATTACHED TO MAIN

Yes

NAME OF CONTRACTOR

R. Marks

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

15-16

1-5-60

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 7169

PERMIT TO TAP SEWER

RECEIVED OF

R. G. Marks

MASSILLON, OHIO,

Oct. 20

19

Frank Kirby

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sewer

SEWER ON THE

North

OF

Auburn N.W.

AVE.

ST. TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

11846

HOUSE NO.

1318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. G. Marks

Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.