Nº 7173

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	Company of the second
HOUSE NO. 3/0		
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE 74' 8' O	
WAS LATERAL AT CURB? YES	and the second of the second o	
	NAME OF CONTRACTOR H. URBHN	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	•
	8' 70	
en van de verske en een ver <mark>w</mark> e een zijn en een ee	So CURB LINE	÷.
SIGNED William C White	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CI	TY L'enaltivant (1891 des Primer à l'Angletique (1818 e Piers)	
BEMARKS	Andrew Krauser (1965) in State and any first two exercises the south plant and a few bottoms of a	

11 047/41

Nº 7173 PERMIT TO TAP SEWER

MASSILLON	, OHIO, A A A 19
RECEIVED OF NAMELY O MARKAU	FEE OF \$ X
FOR WHICH PERMISSION IS GRANTED JULIU BUILD	Cash!
TO TAP ARCU. SEWER ON THE	MARTH
OF TRAGRANT TE ST. TYPE OF STREET	Mark the
THE PREMISES BEING LOT NO. 113 27	. HOUSE NO. 03/0

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR NAME OF CONTRACTOR

Note This permit covers work outside of building only. Anywork in walls of building is subject to Massillon Board of Health Regulations.