Nº 7179

REMARKS.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED // L ~ 2 7 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|------------------------------------------|-------------------------------------------------------|-------------|
| HOUSE NO. 9/6 | | 3 12 |
| SIZE OF PIPÈ USED | DOWN-STREAM TO DITCH AT 103 N. AS OP STREAM | <u> 141</u> |
| | - Roper | |
| WAS ATTACHED TO MAIN MAIN | | |
| SHOW BY DIAGRAM RELATION OF LAT | TERAL TO WALL OF BUILDING SERVED. | |
| en e | 3 1/9 | |
| | | |
| | | |
| | | |
| SIGNED NSPECTOR FOR C | FILED AT ENGINEER'S OFFICE | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

| VOES. | Nº 7179 PERMIT TO TAP SEWER |
|-------|-----------------------------------------------------------------------------------------------------------------------------------|
| | Laundramat MASSILLON, OHIO, 1/17 |
| ian. | RECEIVED OF A A A A A A A A A A A A A A A A A A |
| A. | FOR WHICH PERMISSION IS GRANTED Tank The Margan |
| | TO TAP SEWER ON THE |
| | OF ST. TYPE OF STREET |
| i e | THE PREMISES BEING LOT NO. 2322 , HOUSE NO. 910 |
| | WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE. |
|) | NAME OF CONTRACTOR (1) |

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.