

No. 7187

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-18-59

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

184' WEST OF FIRST M/WEST OF: ^{8' DEEP}

HOUSE NO. 3249

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

R. P. Pender

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



CLEANOUT
190'

8' DEEP
96'
18'

SIGNED Ray Nathan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

15-29
2-11-60

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7187

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/8 19

RECEIVED OF R. Ramsey FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Carroll A. Hingle

TO TAP Water SEWER ON THE 111

OF Rocky Hill AVE. ST. TYPE OF STREET dist

THE PREMISES BEING LOT NO. 8110, HOUSE NO. 3247

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ramsey

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.