

No 7203

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-60

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1203

SIZE OF PIPE USED 4" IN Prop.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

IN Prop 4 1/2' Deep


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

G. D. Lina

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Roy Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Hooked on old House LAT for Garage - 4-6-66
New GARAGE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 7203

PERMIT TO TAP SEWER

House WAS TOrE Down

MASSILLON, OHIO, 9/30 1966

RECEIVED OF A. J. Pearson FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Edward Brinkman

TO TAP from SEWER ON THE 112

OF East Ave. ST. TYPE OF STREET Road

THE PREMISES BEING LOT NO. Pk 9961, HOUSE NO. 7213

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Pearson

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.