Nº 7218

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/11/60 HOUSE NO. 74 - 96	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	and the substitution of the state of the sta
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR H. URBAN
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	70
of the mile of a war on the first term in a	
	CURBLINE UPSTREAM
	18°
SIGNED William C. White	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CIT	un libura ha ka myaj na banya tafani na zinak
REMARKS	

一般存货的设施 新疆 医自己连接性性坏死结束 公司 (E)OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NOTE 17218 COLUMN COMPERMIT TO TAP SEWER

MASSILLON, OHIO, abril 14 19
RECEIVED OF HANNEL & HANNEL FEE OF 5 50
FOR WHICH PERMISSION IS GRANTED JM. CRulik
TO TAP DAW SEWER ON THE LAST
OF 23rd 7110 AVE. TYPE OF STREET HARD DITTER
THE PREMISES BEING LOT NO. 7734-35 , HOUSE NO. 94496
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.